

1st February, 1963

PROGRESSIVE INDEX FOR 1963 SERVICE LETTERS

The following codings are used to indicate the models to which this index applies:—

- | | | | |
|---------|--------------------------|------|--|
| A | "Anglia" Range | D .. | "Zephyr 4/6" and "Zodiac" Mk. III Ranges |
| B | "Consul Cortina" Range | | |
| C | "Consul 315" and "Capri" | G .. | All Passenger Car models |

SUBJECT	MODEL CODE AND SERVICE LETTER No.
Wheels—Hubs
Brakes
Front Axle—Steering Gear
Rear Axle
Frame—Springs
Engine
Gearbox—Clutch	D2, A3, C4
Cooling System	A5, B6, C7
Fuel System
Electrical System
Accessories	A1, G8, G9, G10
Bodywork, Mudguards—Bonnet
General Data

Last Issue: No. 9—Faulty Loudspeakers—"Zephyr 4/6" and "Zodiac" Mk. III Ranges

FAULTY LOUDSPEAKERS

All Models

If a newly installed loudspeaker produces a "harsh" sound output it is probably caused by the speaker cone being distorted off centre. A speaker can be checked for this condition by gently pressing the cone whilst holding it close to the ear. If a slight "scraping" sound can be heard it indicates that the distorted cone is rubbing against the speaker barrel; a correct speaker should be silent under these conditions.

All new speakers should be checked as outlined before installation. This will save unnecessary loss of time and avoid needless owner dissatisfaction.

The foregoing is for Dealer Information Only. Without exception all gratis repairs and replacements are subject to the current Warranty and Policy procedure.