

16th May, 1963

## PROGRESSIVE INDEX FOR 1963 SERVICE LETTERS

The following codings are used to indicate the models to which this index applies:—

- |                                  |  |
|----------------------------------|--|
| A .. .. "Anglia" Range           | D .. "Zephyr 4/6" and "Zodiac" Mk. III |
| B .. .. "Consul Cortina" Range   | Ranges                                 |
| C .. .. "Consul 315" and "Capri" | G .. All Passenger Car models          |

SUBJECT	MODEL CODE AND SERVICE LETTER No.
Wheels—Hubs .. .. .	B38 .. .. .
Brakes .. .. .	A47, B48, D50 .. .. .
Front Axle—Steering Gear .. .. .	.. .. .
Rear Axle .. .. .	.. .. .
Frame—Springs .. .. .	B24 .. .. .
Engine .. .. .	A40, B41, C42, B45, C46, A51, C52, D55 .. .. .
Gearbox—Clutch .. .. .	D2, A3, C4, D23, A47, B48, C49, D54 .. .. .
Cooling System .. .. .	A5, B6, C7 .. .. .
Fuel System .. .. .	.. .. .
Electrical System .. .. .	A12, B13, D14, G15, G16, G17, G18, D29, C30, B31, G32, G33, G34, G35 .. .. .
Accessories .. .. .	A1, G8, G9, G10, G11, G19, G20, G21, G22, B39, B43 .. .. .
Bodywork, Mudguards—Bonnet	D36, D37, D44, D53, G56 .. .. .
General Data .. .. .	G25, G26, G27, G28 .. .. .

Last Issue: No. 55—"Autolite" Spark Plugs—"Zephyr 4/6" and "Zodiac" Mk. III Ranges

## PAINT REPAIRS AND RE-FINISHING PRECAUTIONS

### All Models

To increase efficiency and speed up the "turn-round" of paintwork repairs, infra-red lamps are now frequently used to "force-dry" and harden newly painted areas. When using such equipment, it should be borne in mind that unless precautionary measures are taken, the high temperatures which it is possible to achieve can adversely affect certain body components.

For example, if exposed to high temperatures, plastic parts such as the rear lamp lens will quickly soften and become permanently distorted. P.V.C. materials often used to trim the car interior can also be affected. One component which requires special consideration is a transistor radio, should one be fitted to the vehicle under repair. Wax insulation commonly used in the manufacture of these sets can melt and cause extensive consequential damage if strong local heat is applied.

Care should be taken at all times to shield such parts from the direct heat emitted from these lamps and where practicable, components which could be affected should be temporarily removed from the car, to be replaced on completion of the repair.

*The foregoing is for Dealer Information Only. Without exception all gratis repairs and replacements are subject to the current Warranty and Policy procedure.*