

21st April, 1964

Last Service Letter issued for "Anglia" Range—No. 40—see Section: "Accessories".

STARTER MOTOR BRUSHES



New "Anglia"

Starter motor brush kits containing brushes made of a different material from that previously used, are now available in service.

The new brush kit, Part No. 105E-11057, can be identified by the symbols "CM+O" which appear on the side of each brush. The earlier kit, Part No. E0TA-11057 has the symbols "CM-O" on each brush.

When carrying out a service replacement **ONLY** the latest type brush kit should be used.

Part Name	Part No.	Brush Identification Mark
Brush Kit—(Current)	105E-11057	CM+O
Brush Kit—(Early)	E0TA-11057	CM-O

Similar information to that contained in this Service Letter will also be issued in the following series:—

- Service Letter No. 50 "Consul Cortina" Range
- Service Letter No. 52 "Consul Corsair" Range
- Service Letter No. 53 "Zephyr 4/6" and "Zodiac" Mk. III Range
- Service Letter No. 51 "Consul 315" and "Capri" Range
- Service Letter No. 32 "Thames" 5 and 7 cwt. Van Range
- Service Letter No. 33 "Thames Freighter" (800) Range

The foregoing is for Dealer Information Only. Without exception all gratis repairs and replacements are subject to the current Warranty and Policy procedure.